



BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General							
Zone		Ward No.		Ward Name			
YELAHANKA		7		Byatarayanapura			
Street ID		Street Name		Significant Landmark			
W1133, W0854, W1125, W0852, W1131, W0856, W0858		NA		Kariyanna Layout			
Segment No.		Total Length (m)					
7/S-W1133/S060258		293.44					
Segment Details							
Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	17.35	77.599456	13.042917	77.599453	13.042761	W0852	W0854
2	46.25	77.599995	13.041608	77.599995	13.041190	Rail way line	Dead End
3	229.84	77.600070	13.043432	77.599769	13.041378	Main Road from ring road	Railway Line

Work Details		
History of Road / Lane / Circles		
Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Package No 05 (Consists of 09 Works)	45000000	2016-17
Year	Type of Work	Other Work Type
2016 - 2017	Road	
Tender	Work Details	Job No. / Work Code
Tender	1.Desilting of existing drains2.Construction of Drains3.Providing and laying CC road	007-16-000035, 007-16-000036, 007-16-000037, 007-1
Work Order No.	Work Order Date	Period of Extention
BBMP/EE/BTP/WO/47/ 2017-18	04/01/2018	
Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
14/01/2019	13/01/2022	Yes

Contractor Details		
Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M/s Ram and Company , C.R Girish		0.00
Phone No.	E-Mail ID	
9886110111		

Zone: YELAHANKA

Ward No: 7

Ward Name: Byatarayanapura

Street ID: W1133, W0854, W1125, W0852, W0858

Field Inspection Details

Number of Trees

0

Any Other Information


Name

Pushpalatha.N.D

Date of Inspection

14/01/2019

Remarks


Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA

Ward No: 7

Ward Name: Byatarayanapura

Street ID: W1133,
W0854,
W1125,
W0852,
W11424

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks				
Designation	Approver Name	Date	Target Date	Remark
CE	Sri.R.L.Parameshwaraiah	16/01/2019	13/02/2019	Approved
SE	Basavaraj R Kabade	14/01/2019	13/02/2019	Forwarded
EE	H.T.Mohandas	14/01/2019	13/02/2019	Verified
AEE	H.Ranganath	14/01/2019	13/02/2019	Verified
AE	Pushpalatha.N.D	14/01/2019	13/02/2019	Mobile Verification Done
AE	Pushpalatha.N.D	14/01/2019	13/02/2019	Verified

M.H.M. N.D
16/01/2019

Handwritten signature in green ink
 Assistant Executive Engineer
 Kodigehalli Sub Division,
 Yelahanka Zone, B.E.M.B.
 Bangalore.

Zone: YELAHANKA

Ward No: 7

Ward Name: Byatarayanapura

Street ID: W1133,
W0854,
W1125,
W0852,
W11424, 112



BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	7	Byatarayanapura
Street ID	Street Name	Significant Landmark
W1125, W0852, W1131, W0858	NA	Kariyanna Layout
Segment No.	Total Length (m)	
7/C-W1125/S055733	181.55	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	105.90	77.598840	13.041923	77.599817	13.041923	Main Road	Dead End
2	75.65	77.598889	13.043073	77.599570	13.042927	Cross road	Dead End

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Package No 05 (Consists of 09 Works)	45000000	2016-17
Year	Type of Work	Other Work Type
2016 - 2017	Road	
Tender	Work Details	Job No. / Work Code
Tender	1.Desilting of existing drains2.Construction of drains.3.Providing and laying CC Road	007-16-000035, 007-16-000036, 007-16-000037, 007-1
Work Order No.	Work Order Date	Period of Extention
BBMP/EE/BTP/WO/47/ 2017-18	04/01/2018	
Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
14/01/2019	13/01/2022	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M/s Ram and Company , C.R Girish		0.00
Phone No.	E-Mail ID	
9886110111		

Field Inspection Details

Zone: YELAHANKA Ward No: 7 Ward Name: Byatarayanapura Street ID: W1125, W0852, W1131, W0858

Number of Trees

Any Other Information

Name


0

Pushpalatha.N.D

Date of Inspection

Remarks

14/01/2019

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA

Ward No: 7

Ward Name: Byatarayanapura

Street ID: W1125,
W0852,
W1131,
W0858

Road Condition



This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Sri.R.L.Parameshwarai h	16/01/2019	13/02/2019	Approved
SE	Basavaraj R Kabade	14/01/2019	13/02/2019	Forwarded
EE	H.T.Mohandas	14/01/2019	13/02/2019	Verified
AEE	H.Ranganath	14/01/2019	13/02/2019	Verified
AE	Pushpalatha.N.D	14/01/2019	13/02/2019	Mobile Verification Done
AE	Pushpalatha.N.D	14/01/2019	13/02/2019	Forwarded

Pushpalatha.N.D
AE(29)

Deep
Assistant Executive Engineer
Kodigehalli Sub Division,
Yelahanka Zone, B.B.M.P.
Bangalore.

Zone: YELAHANKA

Ward No: 7

Ward Name: Byatarayanapura

Street ID: W1125,
W0852,
W1131,
W0858